

LCD Door Monitor to LBW-420 with AC to DC converter

LBW-420

LCD Door Monitor	Ac to DC Converter	LBW-420 Connection
	Blue wire (AC-N)	J2-N
	Brown Wire (AC-L)	J2-L
Red wire (BL+)	Red Wire (+VO)	4 to 20mA sensor +
Black Wire (BL-)	Black Wire (-VO)	
Green Wire (SIG -)	Black Wire (-VO)	
White Wire (SIG +)		4 to 20mA sensor -

