


6 conductor 22AWG shielded cable
Up to 500'

LBW-Watchman Remote sensor
adaptor board

J1



J1 is on the opposite
Side and is plugged
Into the control display board

J2

BLU
ORN
GRN
RED
WHT
BLK

Remote Sensor Circuit Board
(inside remote sensor box)

WHT
BLU
ORN
BLK
GRN
RED

White wire and drain wire connected
to the "WHT" terminal