


LBW-50 Control Display board
(mounted inside door)



4 conductor 22AWG shielded cable
Up to 500'

Move Jumpers to connect pins 1 and 2 (far left)
For remote sensor

Green wire and drain wire connected
to the "GRN" terminal

TB1



Remote Sensor Circuit Board
(inside remote sensor box)

